## Defects Induced in Fused Silica by High Power UV Laser Pulses at 355 nm

M. A. Stevens-Kalceff, A. Stesmans, J. Wong

This article was submitted to American Ceramic Society 103<sup>rd</sup> Annual Meeting and Exposition, Indianapolis, IN., April 22-25, 2001

March 23, 2001





## DISCLAIMER

This document was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor the University of California nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or the University of California. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or the University of California, and shall not be used for advertising or product endorsement purposes.

This is a preprint of a paper intended for publication in a journal or proceedings. Since changes may be made before publication, this preprint is made available with the understanding that it will not be cited or reproduced without the permission of the author.

This work was performed under the auspices of the United States Department of Energy by the University of California, Lawrence Livermore National Laboratory under contract No. W-7405-Eng-48.

This report has been reproduced directly from the best available copy.

Available electronically at <a href="http://www.doc.gov/bridge">http://www.doc.gov/bridge</a>

Available for a processing fee to U.S. Department of Energy
And its contractors in paper from
U.S. Department of Energy
Office of Scientific and Technical Information
P.O. Box 62

Oak Ridge, TN 37831-0062 Telephone: (865) 576-8401 Facsimile: (865) 576-5728 E-mail: reports@adonis.osti.gov

Available for the sale to the public from U.S. Department of Commerce National Technical Information Service 5285 Port Royal Road Springfield, VA 22161 Telephone: (800) 553-6847

Facsimile: (703) 605-6900
E-mail: orders@ntis.fedworld.gov

Online ordering: <a href="http://www.ntis.gov/ordering.htm">http://www.ntis.gov/ordering.htm</a>

OR

Lawrence Livermore National Laboratory Technical Information Department's Digital Library http://www.llnl.gov/tid/Library.html

## Defects Induced in Fused Silica by High Power UV Laser Pulses at 355 nm

M.A. Stevens-Kalceff,
Department of Applied Physics, University of Technology, Sydney
P.O. Box 123 Broadway, New South Wales 2007, Australia

A. Stesmans
Department of Physics, University of Leuven
3001 Leuven, Belgium

Joe Wong Lawrence Livermore National Laboratory, University of California, P.O. Box 808, Livermore, CA 94551

Abstract. Point defects induced in high quality optical-grade fused silica by high power (>30 J/cm²) 355 nm laser pulses have been investigated to elucidate the nature of laser damage in transparent optics designed for use at the National Ignition Facility (NIF). Six defects have been identified: the NBOHC (non-bridging oxygen hole center), a STE (self-trapped exciton), an ODC (oxygen-deficient center), interstitial oxygen, the E'<sub>γ</sub>, and E'<sub>74</sub>. The former four defects were identified and spatially resolved in the damage craters using cathodoluminescence (CL) microanalysis (spectroscopy and microscopy). The latter two defects were identified using ESR spectroscopy at cryogenic temperatures. These defects are unlikely to be a prime factor in damage growth by subsequent laser pulses. Their concentration is too low to effect a high enough temperature rise by a volume absorption mechanism.

With the advent of the National Ignition Facility (NIF) [1], now under construction at Lawrence Livermore National Laboratory, Livermore, California [2], and recent industrial interest in far UV lithography for microelectronics and telecommunication [3], laser-induced damage in transparent optics under high power UV irradiation has aroused considerable basic and technological interest in recent years [4]. A surge of multi-disciplinary approaches have been applied not only to elucidate the nature of laser-material interaction leading to damage, but also to provide technically viable and cost effective solutions for prolonging the lifetime of optical components.

Because of its optical properties in the UV region, high quality fused silica (SiO<sub>2</sub>) is the material of choice for transmitting UV laser light (355nm or  $3\omega$ ) to the target in the NIF laser system. The SiO<sub>2</sub>-based optics include the focus lens, diffractive optic plates and the debris shield. Combined with the KDP (potassium dihydrogen phosphate) crystals used for frequency conversion of a Nd:glass laser (at 1.06  $\mu$ m,  $1\omega$ ), these optics make up the NIF final optic assembly [5].

Obscuration loss resulting from laser-induced damage on optical surfaces largely determines the operational lifetime of SiO<sub>2</sub> components on the NIF system. The obscuration arises from two processes: initiation of damage at an absorbing site at or near the surface, and damage growth upon subsequent irradiation [6,7]. Although progress has been made with studies

of polishing contaminations and subsurface damage to minimize the concentration of damage initiation sites on polished silica optics [8,9], the currently attainable defect densities of 1 per  $100 \text{cm}^2$  would still render a non-acceptable number of damage sites on large optics such as the 40 cm x 40 cm lenses used on the NIF laser. A more direct approach is to perform detailed archaeology on the initiated damage sites by determining the material morphology and structural defects induced in fused silica with a view to aiding identification of the damage initiators and to elucidating the mechanism associated with the damage initiation process. This will help to establish a viable, knowledge-based methodology to mitigate or obviate damage growth.

This paper reports the determination of the point defects induced in fused silica by high fluence  $3\omega$  laser pulses using a combination of CL microanalysis [10] and high sensitivity ESR spectroscopy [11]. CL is the non-incandescent emission from a material irradiated with electrons. CL microanalysis in a scanning electron microscope (SEM) enables local variations in the defect structure to be characterized with high sensitivity and high spatial (lateral and depth) resolution [10]. This is the first determination of the microscopic distribution of defects in silica irradiated with high power  $3\omega$  laser pulses and gives insight into the fundamental processes associated with UV irradiation induced defect generation. The corresponding laser-induced morphology and microstructure in SiO<sub>2</sub> are reported elsewhere [12].

The starting fused silica (Corning 7940) substrates were 50mm diameter. x 10mm thick, and optically polished on both surfaces at commercial vendors. For CL measurements 10 mm cubes were cut prior to creation of the laser damage sites. For ESR measurements 2.27mm diameter rods were ultrasonically cored from the starting substrate. During cutting or coring the optical surfaces were protected with a solvent-removable paint. Laser damage sites were created using a 355 nm (3ω beam from a frequency tripled Spectra Physics GCR Nd-YAG laser. The pulse length (FWHM) was 7.5ns and the beam profile was near-Gaussian with an 1/e² diameter of ~0.9mm at the sample plane. The laser repetition rate was 10 Hz [13].

Damage sites were produced exclusively on the laser exit surface [14] using single or multiple pulses with fluences ranging from 30-45 J/cm<sup>2</sup>. Four damage sites were created at the corners of a 5mm square on each cube. For the rods, a pulse of 3 $\omega$  light at 30 J/cm<sup>2</sup> was used to create a single damage site on the exit surface. After protectively covering the laser-damaged surface, a 1 mm thick end disk containing the laser-damaged crater was cut off using a diamond wire saw. Finally, any mechanically induced ESR-active centers (due to cutting and coring) were removed by etching (~60 s) in aqueous HF (5% by volume).

Conventional cw ESR were carried out in the range 4.3-300 K using K-band (~20.5 GHz) and Q-band (~33.5 GHz) spectrometers under conditions of adiabatic slow passage. The amplitude of the modulation (~100 KHz) of the applied magnetic field **B** and incident microwave power  $P_{\mu}$  were restricted to levels where no discernable signal distortion occurred. The latter was particularly pertinent for high-sensitivity low-T observations (requiring  $P_{\mu}$ <0.8 nW at 4.3 K in K-band). Generally, Q-band observations required intense signal averaging (500-1000 scans). Spin densities were determined by double numerical observation of the recorded  $dP_{\mu}/dB$  spectra relative to a comounted calibrated isotropic Si:P spin standard recorded in one trace. The absolute accuracy reached is estimated at <20%, while the relative accuracy may be better then

10 %. The marker signal of  $g_{Si:P}(4.3 \text{ K})=1.99869(2)$  also served as an accurate g reference. More details can be found elsewhere [11].

The CL apparatus and SEM have been described previously [10]. Electron beam power was minimized to reduce electron irradiation induced effects during data collection. The spectra are corrected for total instrument response. CL data from the laser damaged and undamaged fused silica surfaces are significantly different (Fig. 1). Prior to 3ω laser irradiation CL emissions are observed at 1.9 eV and 2.7 eV. Following laser irradiation, the emission intensities increase and in addition, low intensity emissions at 0.97 eV, 2.3 eV and 4.4 eV may also be observed (e.g. Fig. 1(d)). An increase in laser power and/or number of laser pulses enhances the CL emissions consistent with increases in the concentration of associated defects (see Fig. 1). The CL emissions can be identified with a variety of known fundamental defects generated by other energetic irradiations (e.g. electron, ion, x-ray, γ ray, etc [10,15-18] described below.

The 1.9eV emission is associated with the non-bridging oxygen hole center (NBOHC) and attributed to the recombination of electrons in the highly localized non-bridging oxygen band-gap state, with holes in the valence band edge [19]. The low intensity 2.3 eV emission is possibly associated with the radiative relaxation of the self trapped exciton (STE) which is a correlated electron-hole pair localized in a self-induced lattice distortion [20]. Luminescent emissions that are difficult to observe by photo-excitation such as the STE may be observed using CL techniques [21]. Localized thermal annealing of the molten core associated with the laser induced thermal explosion [12] reduces the concentration of competitive non-radiative defects, thereby enhancing the STE emission within the molten core. The 2.7eV and (very low intensity) 4.4eV emissions are attributed to transitions involving oxygen deficient defects (ODC) [15,16]. The 0.97eV emission has been identified as the singlet oxygen transition associated with interstitial neutral molecular oxygen (O<sub>2</sub>) dissolved in the silica host lattice [22].

The microscopic spatial distribution of individual defects can be determined using monochromatic (i.e. energy selective) CL imaging. In Fig. 2. the (a) secondary electron image and (b) 2.7eV, (c) 1.9eV, and (d) 0.97eV monochromatic CL images from laser damaged silica are compared. The 2.7eV emission is spatially correlated with the molten core produced by thermal explosion. CL indicates the molten nodules and micro-fibers (not shown) resulting from the thermal explosion [23] are composed of strained oxygen deficient silica. The 1.9eV emission is more widely distributed and is correlated with the near concentric region of fractured material surrounding the molten core. Strained SiO<sub>2</sub> is a precursor of the NBOHC associated with the 1.9eV emission. Thus CL data is consistent with altered glass topology resulting from enhanced local strain in the vicinity of the laser damaged regions associated with mass loss (spallation) and/or densification (observed high concentration of oxygen deficient centers) due to laser generated shock waves and thermal explosion [12,23]. The 0.97eV emission associated with interstitial molecular oxygen is extremely weak, but clearly attenuated in the laser damaged region, and enhanced at the periphery (Fig.2(d)). The laser induced generation of ODCs results in the concomitant production of interstitial oxygen atoms which are desorbed or diffuse away from the molten core to the periphery of the damaged region during or as a result of the damage process. A proportion of the oxygen atoms have dimerized to form molecular oxygen at the periphery of the damage crater.

Fig. 3 shows a Q-band (f = 33.47 GHz) ESR spectrum of the ten 1-mm silica disks, each containing a damage site created by a pulse of  $3\omega$  light at  $30 \text{ J/cm}^2$ . A central absorption feature having a zero-crossing g-value of  $2.00053\pm0.00004$ , which is characteristic of the  $E'_{\gamma}$  center [15-17] is detected. The total concentration of  $E'_{\gamma}$  defects in the damaged silica disks was determined to be  $(5\pm0.5) \times 10^{12}$ , ie.  $(5.0\pm0.5) \times 10^{11}$  defects/pulse on the average. In addition, a doublet at  $g_c \sim 2.00125$  of splitting  $73\pm1G$  was also present. Its intensity is  $\sim 44\pm4\%$  of the central  $E'_{\gamma}$  signal, ie.  $\sim 2.2 \times 10^{11}$  defects/pulse. This doublet has been studied in detail [24,25], and has been attributed to a hyperfine interaction arising from a H atom substituting one of the back oxygens bonding to the defective Si in the E' center (a H-associated E'-like center). This defect is commonly denoted as  $E'_{74}$ , or H(I) [17]. The source of the H comes from hydrogenic species present in the bulk silica, i.e., Corning 7940 contains 800-1000 wt ppm of OH [26]. Thus, from the total concentrations of  $E'_{\gamma}$  and  $E'_{74}$  determined herein, it appears that  $\sim 44\%$  of all E' created by the  $3\omega$  laser irradiation have a backbonded H.

Given the above OH content in fused silica, the occurrence of the  $E'_{74}$  defects is perhaps not surprising. Yet, interestingly, the ratio  $R = [E'_{\gamma}]/[E'_{74}] \sim 2.3$  would indicate that during the thermal explosion of crater formation, there is a much higher probability for  $E'_{74}$  creation than expected on grounds of atomic concentration. It is likely that during the explosive process, there is violent exchange of H, resulting in a relatively much enhanced  $E'_{74}$  density. It is therefore surprising [25] that no spur of the  $E'_{10.7}$  doublet ascribed to  $HO^{\bullet}Si=O_2$  is observed. An intense search has been carried out at low-T K band, but without success. Thus, within the precursor model  $O_3=Si-Si=HO_2$  of the  $E'_{74}$  defect, it may indicate that during the thermal explosion [23], these strained Si-Si bonds, with H as part of the immediate structure, undergo a substantially higher probability for disruption.

The observed 3\omega laser-induced defects in fused silica are summarized in Table 1 together with their known

Defect	Proposed Structure	Optical spectra (eV) [17,20] Half width(e	V) ESR[15-18]
NBOHC	≡ Si – O •	Abs: $2.0  ext{ (f = 4e^{-4})}  ext{ 0.18}$	$g_c = 2.0095$
		4.8 $(f = 0.2)$ 1.05	
		CL, PL: 1.9 $(\tau = 10.2 \mu s)$ 0.2	
STE	?	Abs: 4.6	
		5.7	
		CL ,PL: 2.3 0.4	
ODC	e.g. <b>≡Si</b> :(Si <b>≡</b> )	Abs: $3.15  mtext{ (f = 1.6e}^{-7})  mtext{ 0.34}$	diamagnetic
	→   ~4.4 Å   ←	5   (f = 0.15)   0.3	
		6.9 (f= 0.1-0.3) 0.4	
		CL, PL: 2.7 $(\tau = 10.2 \text{ ms})$ , 0.3	
		4.4 $(\tau = 4.0 \text{ ns})$ 0.4	
$O_2$	O-O	Abs: 0.978	
		CL, PL 0.97 0.003	
E'γ	$_{\cdot} \equiv \operatorname{Si} \bullet \ldots^{+} (\operatorname{Si} \equiv)$	Abs: $5.85$ (f = 0.14) $0.8$	$g_c = 2.00053 \pm 0.00004$
		No CL and PL observed.	
E'74	$= HSi \bullet^{+} (Si \equiv )$	No CL and PL observed	$g_c = 2.00125 \pm 0.0001$

TABLE 1. Observed 3\omega laser-induced defects in fused SiO<sub>2</sub>: their optical and ESR properties

Notes:  $\equiv$  denotes Si bonding to 3 bridging oxygens in the silica glass structure;  $\bullet$  = an unpaired electron; Abs. = absorption; f = oscillator strength; CL = cathodoluminescence; PL = photoluminescence;  $\tau$  = lifetime; ?, the STE structure is controversial. Values in **bold** are determined in this study and equal to literature values;  $g_c$  is zero crossing g values

optical and ESR properties. Monochromatic CL imaging indicates the absence of interstitial molecular oxygen (0,97 eV emission, Fig. 2(d)) and a concomitant high concentration of oxygen deficient defects (2.7 eV emission, Fig. 2(b))

associated with the molten nodules in the core regions of the craters resulting from the thermal explosion [12,23]. Analysis of the depth profiles of these defects has also been performed using CL spectra collected as a function of electron beam energy, while keeping the beam power constant [27,28]. The results which will be reported in detail elsewhere [30], are consistent with damage initiation at the exit surface. Depth resolved CL microanalysis shows that the concentration of defects is greatest near the laser exit surface and monotonically decays to pre-irradiation levels at ~10 µm depth below this surface.

From the geometry of the damage crater and the number of  $E'_{\gamma}$  centers created per pulse as determined from the ESR measurements, the concentration of this defect, N, induced in the damage crater to a depth of 10 µm is estimated to be ~2.5 x  $10^{17}$ /cm³ (far below the maximum density (~5 x  $10^{19}$  /cm³ that may occur in bulk fused silica [30]). With this defect concentration, the known oscillator strength and spectral width given in Table 1, and using the Smakula's equation [31], an absorption coefficient,  $\alpha$ , of ~10 cm¹ is estimated for the 5.85 eV absorption band of the  $E'_{\gamma}$  center. Assuming volume absorption, the temperature rise is given by  $T = \alpha.F / [\rho.c_p]$ , F is the laser fluence in J/cm²,  $\rho$  is the density of fused silica and  $c_p$  is the heat capacity. With  $\alpha = 10$  cm¹, F = 10 J/cm²,  $\rho = 2.2$  gm/cm³ and  $c_p = 0.77$  J/gm/K for fused silica [26], a temperature rise of ~60 K is obtained. This estimate merely shows that the concentration of  $E'_{\gamma}$  defects created in the damage initiation process is too low to result in high enough energy absorption by induced defects, such as the  $E'_{\gamma}$  center and others listed in Table 1, are a prime factor for damage growth. Other mechanisms such as local E-field enhancement at cracks (Fig. 2a) and micro-pores [32], avalanche ionization, multi-photon absorption and other non-linear processes have to be considered [33, 34].

This work was performed under the auspices of the U.S. Department of Energy by the University of California, Lawrence Livermore National Laboratory under contract No.W-7405-ENG-48. M.A.S-K. gratefully acknowledges the Australian Research Council for financial support.

- 1. E.M. Campbell, Fusion Technology 26, 755 (1994).
- 2. C. Seifa and D. Malakoff, Science 289, 1126 (2000).
- 3. H. Hosono and K. Kawamura, in *Defects in SiO<sub>2</sub> and Related Dielectrics: Science and Technology*, edited by G. Pacchioni, L. Skuja, and D.L. Griscom, (Kluwer Academic Publisher, Boston 2000), p. 213.
- 4. See for example, Proc. 32<sup>nd</sup> Ann. Symposium of Optical Materials for High Power Lasers, Boulder CO, Oct, 16-18 (2000) (to be published).
- 5. M.R. Kowlowski, R. Mouser, S. Maricle, P. Wegner, and T. Weiland, SPIE Proceedings 3578, 436 (1999)
- A. Salleo et al., SPIE 3244, 341 (1998); ibid, 3578, 456 (1999).
- 7. S.G. Demos and M.R. Kozlowski, SPIE 3933, 316 (2000); ibid 4102, 106 (2000).
- 8. M.R. Kozlowski, J. Carr, I. Hutcheon, R. Torres, L. Sheehan, D. Camp, and M. Yan, SPIE 3244, 65 (1997).
- 9. R.C. Estler, N. Nogar, R. Schnell, NIST Spec. Publ. 775, 183 (1989).
- 10. M.A. Stevens-Kalceff, Phys. Rev, Lett. 84, 3137 (2000).
- 11. A. Stesmans, Phys. Rev. **B48**, 2418 (1993)
- 12. Joe Wong et al, to be published.
- 13. L. Sheehan, S. Schwartz, C. Battersby, R. Dickson, R. Jennings, J, Kimmons, M. Kozlowski, S. Maricle, R. Mouser, M. Runkel, and C.

## Weinzapfel, SPIE vol. 3578 302, (1998)

- 14. N.L. Boiling, M.D. Crisp and G. Dube, Appl. Optics 12(4), 650 (1973)
- 15. D.L. Griscom, Nucl. Instrum. Meth. Phys. Res. B46, 12 (1990).
- 16. D.L. Griscom, J. Ceram. Soc. Japan 99, 923 (1991)
- 17 L. Skuja, J. Non-Cryst. Solids 239, 16 (1998).
- 18. N. Matsumami and H. Hosono, Phys. Rev. B60, 10616 (1999)
- 19. L. Skuja, J. Non-Cryst. Solids 179, 51 (1994)
- 20. A.N. Trukhin, Ref. 3, p. 235; ibid, J. Non-Crystal. Solids, 149, 32 (1992)
- 21. L. Skuja, Ref. 3, p. 73
- 22 L. Skuja et al. Phys. Rev. **B58**, 14296 (1998)
- 23. M. D. Feit, L. Hrubesh, A.M. Rubenchik and Joe Wong, SPIE Proc. (2000), (to be published)
- 24. J. Vitko, J. Appl. Phys. 49, 5530 (1978).
- 25. T.E. Tsai and D.L. Griscom, J. Non-Cryst. Solids 91, 170 (1987)
- 26. See hpfs@Corning.com, for Corning 7940 specification, March (1999).
- 27. B. Yacobi an D. Holt, Cathololuminescence Microscopy of Inorganic Solids, 1st ed. 1990, New York, Plenum Press
- 28. M. Goldberg, T. Barfels, and H. Fitting, J. Anal. Chem. 361, 560 (1998).
- 29. M.A. Stevens-Kalceff and Joe Wong, to be published.
- 30. M. Antonini, P. Camagni, P.N. Gibson, and A. Manara, Rad. Effects 65, 41-48, 281 (1982).
- 31. E.J. Friebele and D.L.Griscom, Radiation effects in Glass, in *Treatize on Materials Science and Technology*, edited by M. Tomozawa and R.H. Doremus, vol. 17 (Academic Press, New York, 1979), pp. 257-351.
- 32. N. Bloembergen, Appl. Opt. 12, 661 (1973).
- 33. J. Jasapara, A.V.V. Nampoothiri, W. Rudolph, D. Ristau and K. Starke, SPIE Proc. 4222 (2001)
- 34. F.Y.Genin, A. Salleo, T.V. Pistor, and L.L. Chase, J. Opt. Soc. Am. A (2001) (in press)




Fig. 1. Visible CL spectra (25keV, 1.5nA) from 150 x 200  $\mu$ m<sup>2</sup> regions of fused silica: (a) undamaged area, and (b) 3 $\omega$  damaged area, 30 Jcm<sup>-2</sup>, 1 pulse, (c) 30 Jcm<sup>-2</sup>, 2 pulses and (d) 45 Jcm<sup>-2</sup>, 1 pulse. Gaussian components are arrowed.




Fig. 2. (a) Secondary electron image, (b) 2.7~eV, (c) 1.9~eV and (d) 0.97eV monochromatic CL images from a damage crater on the exit surface of fused silica induced by one pulse of  $3\omega$  light at  $45Jcm^{-2}$ .




Fig. 3. Q-Band ESR spectrum of  $3\omega$  damaged fused silica recorded at 10K. The signal is from ten 1-mm thick disks, each with a damage site initiated with a shot of  $3\omega$  light at 30 Jcm<sup>-2</sup>.